
## ELECON REVIS



Broken Curbs In
Montana Are
Repaired & Protected
With DuraFill,
DuraQuartz,
FLEXICLAD PC &
ENESEAL CR



After removing the loose material and cleaning the areas, the curbs were repaired with ENECRETE DuraFill & DuraQuartz. All of the curb/building joints were filled with FLEXICLAD PC to allow for expansion. A final overcoat of ENESEAL CR was used to provide an attractive appearance.





