



Severely Cavitated Turbine Shaft Repaired Using METALCLAD & DuraTough

A turbine shaft at a utility in the midwestern U.S. was badly damaged by cavitation. The ENECON specialists in the area recommended a repair using both **METALCLAD DurAlloy** and **FLEXICLAD DuraTough**.

First the shaft was grit blasted, cleaned and repaired with **DurAlloy** to build up the diameter back to original size. The entire shaft was then brush blasted and coated with **DuraTough DL** to prevent future cavitation damage.

A great two-product, ENECON solution to this problem that will provide years of trouble-free service!



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com