



After grit blasting, leaks repaired with DurAlloy.



DuraWrap Primer applied.



DuraWrap Carbon Fiber, impregnated with DuraWrap Polymers, being wrapped around pipe section.



**Client:** Waste water treatment plant.  
**Location:** Northeastern U.S.  
**Problem:** Corroded & leaking main influent pipe.  
**Solution:** Repair leaks with *DurAlloy*; reclaim pipe with *DuraWrap Carbon Fiber Pipe Wrap System*.  
**Cost:** \$40,000 total turn-key project.  
**Savings:** \$100,000+ replacement cost.



Completed DuraWrap System.

6 Platinum Court • Medford, NY 11763  
Toll Free: 888-4-ENECON • Phone: 516-349-0022 • Fax: 516-349-5522  
www.enecon.com • info@enecon.com