

Municipal Storm Water Drain Pump Repaired & Protected With CeramAlloy

Problem: Debris such as sticks, trash and silt eroded this municipal storm water drain pump bowl's veins (pg.1). The debris also broke the impeller's veins (pg. 2).



Solution: A new 'skeleton' for the veins was constructed by welding metal bars and wire mesh. CeramAlloy CP+AC was used to rebuild the veins and CeramAlloy CL+AC protected all the internal pump surfaces.

Savings: A new pump has a 24 week lead time. The ENECON solution was completed in 1 week and provided over \$50,000 in savings.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com

ENECON® NEWS



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON® (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com