## ERECON REVIS







This Brazilian paper mill stock pump was severely damaged after 12 years of continuous use. The mill's engineers sent the pump out to two separate pump repair companies who advised that this pump was "unrepairable" and suggested replacement as the only viable option.



A new pump, however, would cost over \$20,000.

The ENECON Brazil
Engineering Team was then
contacted to see if they
could tackle this project.
They suggested a standard
CeramAlloy/DurAlloy pump
repair procedure. The
plant's engineers agreed



and this pump was expertly repaired and protected from future erosion-corrosion damage in just a few days for less than 1/3 the cost of a new pump.



700 Hicksville Road • ENECON Center Suite 110 • Bethpage, NY 11714 Toll Free: 888-4-ENECON • Phone: 516.349.0022 • Fax: 516.349.5522 Website: www.enecon.com • Email: info@enecon.com