



This damaged concrete effluent tank is located at an explosives company in Australia. The effluent water inside of this tank contains cyanide and ammonium nitrate.

After years in service the concrete floor and wall were showing signs of deterioration After the from chemical attack. **ENECON's** Exclusive **Distributor in** Australia was contacted and asked to provide a solution to this problem.

All the effluent water was

drained from the tank and the existina pipework leading into the tank was temporarily disconnected.

The entire surface of the floor and wall were rebuilt to the original specification usina ENECRETE DuraQuartz.

DuraQuartz fully cured, two coats of CHEMCLAD XC were applied to the floor and wall to prevent future chemical attack.









6 Platinum Court • Medford, NY 11763 Toll Free: 888-4-ENECON® (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522 www.enecon.com • info@enecon.com

Copyright ©2023 by ENECON®Corporation.

REPAIR - DON'T REPLACE