NECON REVIS





These outdoor courtyard steps in first pressure Seattle, WA have heavy foot traffic all day long from general sidewalk use and office building/restaurant loose material. entry ways in the courtyard. Over the past decade, the condition of these steps has

deteriorated with

cracks and

concrete loss.

The building's maintenance engineers contacted the local broken and loose **ENECON Field Engineering** Specialist to survey the step's condition and provide a cost effective solution to repair and protect these steps to prevent slip and fall accidents.

The steps were washed to remove years of dirt and debris. Next the cracks were "Vground" to remove

DuraQuartz was then applied to fill and smooth all the cracks. Several other areas required larger **DuraQuartz** repairs to fill large holes, a lengthy crack on a riser and replace and secure several pieces much like a jigsaw puzzle.

Finally, two coats of DuraFill and a blended colored quartz aggregate were applied in the typical broadcast fashion.













6 Platinum Court • Medford, NY 11763 Toll Free: 888-4-ENECON® (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522 www.enecon.com • info@enecon.com