



When All Else Failed, Only ENESEAL HR Stopped the Leaks in Israel



As reported by our Field Engineering Specialist for the ENECON Distributor in Israel...

“These pictures show a joint between an old and a new building. Water was leaking through the joint. They tried all kinds of solutions (silicone, tar, etc.) with no success”.

Although every-thing they could come up with in the way of conventional approaches and materials was tried, none proved successful.

The leaks were finally stopped; but -- Only ENESEAL HR did the job!



700 Hicksville Road • ENECON Center Suite 110 • Bethpage, New York 11714
Toll Free: 888-4-ENECON • Phone: 516.349.0022 • Fax: 516.349.5522
Website: www.enecon.com • Email: info@enecon.com