




Location: Southern Florida

Problem: Extreme rust, corrosion & peeling paint on generator cabinets as well as elevated internal cabinet temperatures from the sun.

Solution: After preparing the surface with a wire wheel, 3 coats of ENESEAL CR were applied to provide corrosion resistance followed by 2 coats of ENESEAL HR to give heat refractive properties to the cabinet roofs.





Southern Florida Sewage Plant Uses ENESEAL to Stop Rust and Reduce Heat on Generator Cabinets



6 Platinum Court • Medford, NY 11763 Toll Free: 888-4-ENECON[®](888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522 www.enecon.com • info@enecon.com

Copyright ©2017 by ENECON[®] Corporation.

