ELECON® NEVS



40 Units of ENECRETE Durafill Used to Repair Cracked Concrete Floors in 8 Costa Rican Warehouses



Problem: 20 year old warehouse concrete floors were severely cracked due to several factors, including excess weight being stored.

Solution: It was decided that ENECRETE® DuraFill®, mixed with locally sourced quartz sand, was the most cost effective course of action to solve this problem. All of the cracks were first opened up mechanically with a grinding wheel. The loose material was vacuumed up. The DuraFill® / sand mixture was then poured into the cracks. Before the DuraFill® was fully cured it was sanded down seamlessly to the floor's height.

Cost: This project was in excess of \$85,000 USD saving the customer hundreds of thousands of dollars in new concrete costs.









