



This indoor atrium staircase at a prestigious eastern U.S. university was falling into disrepair. The old vinyl tiles were detaching from the substrate causing an eyesore as well as safety concerns for students and faculty alike.

The local ENECON Engineering Specialist was contacted to help find a fast and economical solution.



The vinyl tiles were manually removed from the staircase. The tile's

mastic was then mechanically removed from all areas and the metal step substrate was roughened.

**ENECRETE DuraQuartz** was used to repair any damaged areas followed by a two coat system of **ENECRETE DuraFill** with an aggregate broadcast for slip resistance in this high foot traffic area.

The university was very pleased with the results and future **Repair - Don't Replace** projects have already been scheduled.

## University Repairs & Protects Interior Staircase With ENECRETE<sup>®</sup> DuraQuartz<sup>®</sup> & DuraFill<sup>®</sup>



6 Platinum Court • Medford, NY 11763  
Toll Free: 888-4-ENECON<sup>®</sup> (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522  
www.enecon.com • info@enecon.com