

Pennsylvania Gas Station Pump Island Curbs Rebuilt With DuraQuartz & DurAlloy



A very popular chain of Pennsylvania gas stations & convenience stores was experiencing severe corrosion and erosion on their gas pump island curbs. It was a potential hazard to customers and employees in addition to being very unsightly.

The maintenance management team contacted the local

ENECON Field Engineering Specialist to provide a fast, economical and proven solution to this problem.

After all the loose material was removed and the area cleaned, the concrete curb was rebuilt with *ENECON DuraQuartz*. The half-round metal curb edging was rebuilt with METALCLAD DurAlloy.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com