




CeramAlloy Repairs Salt Water Filter at Major Spanish Natural Gas Company









After protecting the mechanical areas, the surface was prepared by grit blasting.

First, CeramAlloy CP+AC was used to rebuild all pitted surfaces.

CeramAlloy CL+AC Grey was then applied.



Followed by the final coat of CeramAlloy CL+AC Blue.


After this repair was completed, the engineers agreed that a flexible joint at the bottom of the filter would be needed.

So FLEXICLAD DuraTough DL was applied to create a durable, yet flexible seal.









700 Hicksville Road • ENECON Center Suite 110 • Bethpage, New York 11714 Toll Free: 888-4-ENECON • Phone: 516.349.0022 • Fax: 516.349.5522 Website: www.enecon.com • Email: info@enecon.com

Copyright © 2006 by ENECON® Corporation.

MT-082_CeramAlloy_Repairs_Salt_Water_Filter_at_Spanish_Natural_Gas_Company.pdf