ELECON REVIS



Veteran's Hospital Solves Slipping Problems with ENECRETE DuraQuartz



This large Veteran's **Hospital in Texas** had a slipping problem in some of their bathrooms. Water from the shower areas would run into the bathrooms creating slip hazards near the sinks and stalls. They needed a way to contain the water in the showers

but still permit wheelchair access to (bumps) to keep the the shower areas when needed.

Furthermore, since these showers were used constantly. they could not shut them down for a prolonged period. Any solution would have to be quick, cost effective and odor-free.

They called their local ENECON **Regional Sales Director who** recommended constructing shallow maintenance staff.

containment burms water from spilling into the bathroom areas. These burms are about 20 inches wide and about 2 inches high at the center. They were tapered to a "featheredge" in order to permit wheelchairs to be easily rolled over them.

27 Units of **DuraQuartz** were used to treat 17 shower rooms to the complete satisfaction of the hospital









700 Hicksville Road • ENECON Center Suite 110 • Bethpage, New York 11714 Toll Free: 888-4-ENECON • Phone: 516.349.0022 • Fax: 516.349.5522 Website: www.enecon.com • Email: info@enecon.com