

ENESEAL® To The Rescue at Russian Chemical Plant



A chemical plant in the central region of Russia was experiencing corrosion issues. Over 3 years ago, exterior metal components including chemical tanks, gas lines, railings and more, were painted with conventional paint. As time went by, the corrosion increased creating deterioration as well as an eyesore.

The plant engineers were looking for a long-term protection solution.

Two years ago, the plant engineers had used ENESEAL CR on some of their inside equipment and the results have been exceptional. Grit blasting is prohibited in the plant which made ENESEAL CR even more ideal because only pressure washing preparation can be used.

Two coats were applied and the plant management is just as happy with the outdoor results as they have been with the indoor ones.









6 Platinum Court • Medford, NY 11763 Toll Free: 888-4-ENECON® (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522 www.enecon.com • info@enecon.com

Copyright ©2013 by ENECON[®] Corporation.

REPAIR - DON'T REPLACE