


ENECRETE DuraQuartz Repairs Crumbling Concrete at Turkish Cement Factory



One of the largest cement factories in Turkey was having trouble with leaking silos where raw materials are stored. Two silos carrying a total of 7,000 tons of hot raw material were leaking through worn concrete walls at the silo bases. The engineers at the cement factory have tried a number of different concrete repairs over the years but none of them solved the problem.

The old, ineffective concrete patches were removed and a rotary hammer was used to prepare the areas to be repaired. Twenty-nine units of **ENECRETE DuraQuartz** were then used to make the repairs.

Engineers at the cement factory were astonished with the results – and this coming from people who understand concrete repair better than most.

6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON® (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com