ELECON® NEVS



In 2004, ENECON was contacted by maintenance engineers to provide a solution for crumbling concrete steps at a stadium in the western U.S. 12 years and hundreds of sporting events and concerts later, the DuraQuartz step repair looks like it did the day it was installed.

A repair like this may be small, but it is one of the most important repairs a facility can make.

Damaged steps account for millions of injuries a year.

Maintenance engineers want to do their best to prevent these types of accidents on their properties.

ENECON is there to help.







