

Popular Cocktail Bar In Cyprus Uses ENECRETE DuraFill To Repair Crumbling Floor



All the loose flooring material is removed



The substrate is prepared



DuraFill and decorative stone is applied



The flooring material at this cocktail bar in Cyprus was deteriorating and coming loose. This was both unsightly and a potential tripping hazard. The bar's owners needed to find a quick and effective solution to solve this problem.

ENECON Cyprus was contacted to provide a solution. They had to remove the crumbling floor and replace it with fast curing system that could withstand the daily foot traffic from the bar's patrons. The bar wanted something aesthetically pleasing with no odor so as not to disrupt their business.

The existing, failing flooring material was removed and the

concrete substrate was cleaned and left to dry. **ENECRETE DuraFill** was applied by brush and roller to the concrete as a primer. The owners had chosen a decorative stone that was mixed with the *DuraFill* and applied to the floor. Once this step of the application was completed, a layer of *DuraFill* resins was rolled onto the floor to seal it and provide maximum protection.

Within 48 hours ENECON Cyprus was able to deliver the bar's owners a completely new floor that not only looked great but also had much better resistance to foot traffic and spilled drinks than the previous material.