

## DuraFill® & CHEMCLAD® SC 'Heal' Crumbling, Unsafe Hospital Steps

These crumbling employee entrance/exit steps at a local Montreal hospital were unsightly and a potential safety hazard. The hospital called in the local ENECON® Distributor to find a fast and cost effective solution.

After manual preparation, the steps were repaired and rebuilt in certain areas with DuraFill® mixed with locally sourced quartz sand. CHEMCLAD® SC Gray and Safety Yellow were used as top coats while a quartz sand broadcast was back-rolled in to provide slip resistance.



6 Platinum Court • Medford, NY 11763  
Toll Free: 888-4-ENECON® (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522  
[www.enecon.com](http://www.enecon.com) • [info@enecon.com](mailto:info@enecon.com)