

CHEMCLAD SC NSF Approved For Potable Water Applications Protects Drinking Water Clarifier At Chemical Plant In New Jersey

This clarifier at a water treatment plant in New Jersey (approximately 80 feet long x 17 feet wide x 15 feet deep) was in need of critical repairs.

The clarifier is about 30 years old, with severely eroded concrete with aggregate protruding up to ½ inch. There were also several cracks that

leaked through to adjacent tanks and through exterior walls, degrading those areas as well.

The client wanted the leaks stopped and the concrete sealed to retard future degradation.

ENECON had completed various smaller projects

at this plant to seal and protect other concrete containment areas and waste water clarifiers with great success.

This \$110,000+ project took 4 weeks to complete, due to schedules onsite and weather problems, but the client was very pleased.

There are 5 more of these tanks and one will be completed every year for the next 5 years.

ENECON was awarded another tank repair and protection project worth over \$105,000+ as a result of this job.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com