

CeramAlloy Protects Nuclear Power Plant Pump



Over 3 years ago this large main circulating pump, 1 of 12 at this Mid-Atlantic region nuclear power plant, had been coated with 3 coats of CeramAlloy™ CL+AC.

This pump had been operating continuously in very corrosive, brackish water conditions.

During a scheduled maintenance shut-down the plant engineers discovered that the CeramAlloy™ CL+AC was in virtually perfect condition.

Following minor touch-ups, the pump was put back in service for another 3-year cycle.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com