




Mexico's Largest Petrochemical Company Specifies METALCLAD CeramAlloy for Repairs to Heat Exchanger Tube Sheets



- Client:** Petrochemical Plant
- Location:** Mexico
- Problem:** Severely corroded heat exchangers.
- Solution:** Grit blasting followed by CeramAlloy CL+AC, CeramAlloy CP+AC and final top coat of CeramAlloy CL+AC.
- Cost:** \$20,000 product and labor.
- Savings:** Previous repair methods were approximately \$250,000. The ENECON Solution was less than 10% of those costs!

6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com