

Chilean Hospital Pumps Brought 'Back to Life' with CeramAlloy[®] and CHEMCLAD[®]



This hard water pump at a hospital in Chile was only averaging a few months in service before maintenance would have to be performed to repair deep erosion / corrosion damage.



After thoroughly grit blasting, all deeply damaged areas were repaired with CeramAlloy CP+AC. Two coats of CeramAlloy CL+AC were then applied to provide erosion / corrosion resistance.



1. The pump casing before being refurbished.

2. The pump casing after grit blasting.

3. The pump casing was coated with CHEMCLAD SC which protects from future erosion / corrosion.

6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com