

## Hospital Entry Staircase Is 'Healed' With DuraQuartz & DuraFill




After only 12 years in use this staircase was cracked, crumbling and badly stained from the harsh elements and routine de-icing efforts during the harsh Colorado winters.

Stair noses were broken on several stairs and there were multiple areas of missing concrete.

The stairs were first cleaned with lemon juice to remove the staining. Then DuraQuartz was used to repair the stair noses and voids in the concrete. Seams and expansion joints were taped and three coats of a Durafill broadcast system were rolled out.

This application remedied the public safety hazard but it was an aesthetic improvement referred to as "better than 100%" by the client. This staircase is now an area of pride.

Close to \$15,000 was saved by using this ENECON method over a complete staircase replacement.



6 Platinum Court • Medford, NY 11763  
Toll Free: 888-4-ENECON<sup>®</sup> (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522  
[www.enecon.com](http://www.enecon.com) • [info@enecon.com](mailto:info@enecon.com)