



## Water Pump Casing Protected With ENESEAL CR



A local water authority in Mexico that supplies drinking water to the communities in the surrounding area had three water pumps that needed maintenance. To prevent further atmospheric corrosion damage to the pump's metal exterior casing, maintenance engineers asked the local ENECON Distributor to provide a solution.

The pumps were disassembled and the various pieces of the exterior casing were lightly grit blasted to remove any old paint, dirt or rust. Two coats of **ENESEAL CR** in Safety Yellow were then applied to protect the casing's surfaces.



6 Platinum Court • Medford, NY 11763  
Toll Free: 888-4-ENECON<sup>®</sup> (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522  
www.enecon.com • info@enecon.com