

Texas Waste Water Treatment Plant Solves Concentrated Sulfuric Acid Attack Problem With CHEMCLAD XC & DuraQuartz

98% Sulfuric Acid had badly damaged the concrete floors around the acid storage tanks. Many repairs were tried but these provided only temporary relief.

The plant engineers turned to their local ENECON Fluid Flow Systems Specialist based in South Texas.

ENECRETE DuraQuartz was immediately recommended for repairing the damaged concrete and then **CHEMCLAD XC** to completely re-

surface the entire floor area to protect it against future acid attack.

DuraQuartz and CHEMCLAD are a great combination whenever chemicals create problems on concrete, stone, tiles, metal, etc.

Most repairs can be completed very quickly with minimum inconvenience and down-time.

Of course, they are 100% solids systems that give off no offensive odors or fumes.

