

ENECRETE, ENECLAD & CHEMCLAD Repair & Protect Containment Areas at Chilean Power Plant




Client: 900 Megawatt Thermoelectric Plant

Location: Chile

Problem: Corrosion of 3 concrete acid containment areas.

Solution: After mechanically cleaning concrete walls, ENECRETE DuraFill was used to repair all damaged areas. ENECLAD CFS was then applied followed by two coats of CHEMCLAD XC for maximum protection.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com