



Desalination Plant in Cyprus Uses ENECRETE & CHEMCLAD to Stop Sulfuric Acid Attack

Client: Desalination Plant

Location: Cyprus

Problem: Sulfuric acid pump drip had badly damaged the cement base it sat on.

Solution: Damaged concrete was repaired with ENECRETE DuraQuartz. CHEMCLAD P4C was applied as a primer to the concrete. Two coats of CHEMCLAD XC we then applied to provide optimum chemical resistance.

Savings: This project was completed in 3 days much to the delight of the plant managers who saved thousands of dollars by avoiding a full replacement.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com