


Deteriorating Containment Areas, Pump Bases & Sumps Repaired at Northern California Chemical Company

When previous coatings had failed numerous times, a chemical company located in Northern California called on ENECON to protect its badly deteriorating containment areas, pump bases and sumps.

The surfaces were first prepared by removing the old and delaminated coatings. All surfaces were later primed with ENECRETE DuraFill followed by two top coats of CHEMCLAD XC for

unrivaled chemical attack protection.

This turnkey project was completed in less than two weeks with no plant down-time. In addition to helping the customer comply with California chemical containment area codes, this application will provide unsurpassed chemical attack protection for many years to come.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com