




Protecting the Past and Future at a Chicago Museum with CHEMCLAD



This Chicago museum, which is over a century old, has some of the world's most priceless art and artifacts. Repair and maintenance of the building are of the utmost importance.

The museum had a pump failure and subsequent flood in a 2nd floor mechanical room. They had to discard everything from carpets to computers in the office that was underneath it. They needed a solution to fix the current problem and protect them in case of future failures. They called in their local ENECON Field Engineering Specialist.

The prescribed solution was CHEMCLAD SC. After the floor was mechanically prepared and pressure washed, a primer coat of CHEMCLAD P4C was applied followed by two coats of CHEMCLAD SC in gray. The raised sections of the floor were highlighted with CHEMCLAD SC in safety yellow for safety purposes.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com