

ENECRETE & ENESEAL Bring Degrading Hospital Staircase 'Back to Life'

This prestigious medical center located in the Northeastern U.S. had a severe problem with their main entry steps. Replacing them was not an option as they were an important part of the hospital's classic 1950's style of architecture.

After determining that the steps were structurally sound and not a danger to the public, the hospital's engineers then needed to find a cost effective, viable repair and protection system. The local ENECON Engineering Specialist was contacted.

He recommended that a combination of *ENECRETE DuraQuartz* and *DuraFill* as well as *ENESEAL CR* be used over a 5 day period to repair and protect these steps.

After thoroughly cleaning the substrate, *DuraQuartz* was first used to rebuild the deteriorating stair structure.

ENESEAL CR was then used to protect the concrete from further corrosion as well as create a uniform look. *DuraFill* was then used on the top of the step surfaces to provide a slip-resistant safety surface.

The hospital's engineers, as well as the administrators, were ecstatic with ENECON's ability to not only repair and protect the steps, but maintain the important architectural integrity of the building.



A Job Well Done!

6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com