



## ENECRETE DuraFill & CHEMCLAD XC Salvage Floor at Polish Food Plant



This large, international margarine producer, located in Poland, had a severe problem with some of their floor areas. These areas, which were under processing equipment that *could not be moved*, had deteriorated due to the aggressive chemicals that continuously drop on the concrete floor.

A variety of contractors were called in to provide a cost effective solution but nobody was able to figure out how to accomplish this repair project without moving the equipment.

Enter ENECON Poland...

They recommended cleaning the areas and then pouring out ENECRETE DuraFill mixed with locally sourced fine aggregates. Then two coats of CHEMCLAD XC were applied to provide long-term chemical protection to these floor areas.

The entire project took just 7 days to complete with minimal disruption to plant operations.

6 Platinum Court • Medford, NY 11763  
Toll Free: 888-4-ENECON • Phone: 516-349-0022 • Fax: 516-349-5522  
[www.enecon.com](http://www.enecon.com) • [info@enecon.com](mailto:info@enecon.com)