


Moroccan Flour Manufacturer Uses DuraFill to Repair & Protect Their Floors

Client: *Flour Manufacturer*

Location: *Morocco*

Problem: *1000 sq meter concrete and tile floors in factory warehouse were spalled, cracked, and pitted.*

Solution: *All loose material was removed and holes, cracks, and joints were repaired / filled with ENECRETE DuraFill. A thin coat of DuraFill was used to level the floors then a final DuraFill topcoat, tinted gray in the field, was applied.*



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON® (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com