



Southeastern U.S. Garbage Transfer Station Uses ENECRETE® DuraFill® to Repair Damaged Concrete Floor



Client: Southeastern U.S. municipal garbage transfer station.

Problem: Concrete degradation up to 12" deep from heavy equipment traffic and garbage pile up.

Solution: ENECRETE® DuraFill® with locally sourced quartz sand.

Savings: 9 units of DuraFill saved the municipality lengthy down-time and new concrete costs. The area was back in service in 24 hours.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON® (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com