

## Prestigious Hospital in Montreal Solves Serious Safety Problem With a SuperBond Non-Skid System



The ENECON Distributor in Montreal, Martin DeSerres, was confronted with a difficult problem. The conventional non-skid tape on these marble steps at a local hospital was constantly coming up due to the very heavy traffic on the stairs. Repeated attempts to re-apply these tapes proved ineffective.

The hospital needed a long-term solution for this critical safety problem, but there was an additional requirement: there could be no dust generated during any surface prep procedure. Furthermore, there could be no noise or odor during the application.

The answer? ENECLAD SuperBond coupled with a fine aluminum oxide aggregate. After a thorough detergent cleaning, the area was dried, masked-out and SuperBond was applied. An aluminum oxide aggregate was then tamped into the SuperBond and the area was allowed to cure for 24 hours.

No mess, no fuss, no dust, no noise, no smell...  
**NO PROBLEM.**

