



Generator Building Floor Repaired / Protected with DuraQuartz & ENECLAD FPS



Application of P4C

The city of Cape Coral is one of the largest cities in Southwest Florida. The floor paint in one of their generator buildings was failing. The plant engineers turned to their local ENECON representatives for help to provide a longer term solution to this recurring problem.

He recommended first using **ENECRETE DuraQuartz** to repair all the damaged areas on the concrete floor, followed by the application of the P4C primer and then **ENECLAD FPS**. **ENESEAL CR** in 'safety

yellow' was then applied to delineate any trip hazards.

The generator facility is a several million dollar investment for the city and the concrete floors were in need of repair and protection.

The entire project was completed in three days with city personnel and on-site support provided by the local ENECON Field Engineer.



ENECLAD FPS



Total material cost for this project was just under \$9,000 and the plant engineers have already ordered additional material to do three smaller buildings at their facility. In addition, the plant will be coating two much larger buildings this winter which are approximately double the size of this one.

6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com