

Southern California Detention Center Stops Cooling Tower Corrosion with ENESEAL CR



- Client:** Major metro area detention center.
- Location:** Southern California.
- Problem:** Cogen plant cooling tower was corroding at an accelerated rate.
- Solution:** After surface prep that consisted of power washing and grit blasting, ENESEAL CR was applied to provide long term corrosion resistance.
- Cost:** \$15,000 in product.
Labor provided by plant personnel.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com