

Pharmaceutical Company Uses ENESEAL CR to Protect Roof-Top Air Handler Fans & Ductwork



Client: Pharmaceutical Company

Location: Eastern U.S.

Problem: Environmental corrosion was causing severe rust conditions on the fans, pads and ductwork.

Solution: Not only did the building engineers want to stop the rust but they also required a uniform, medium gloss, brush/roller mark-free finish. ENESEAL CR was chosen to satisfy all of the above criteria.

This work was done over the course of 5 months and the engineers we so pleased with the results it has lead to many other applications at the facility.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com