







## CeramAlloy Selected For Heat Exchanger Repairs At Various Petrochemical Plants in Belgium

CeramAlloy has been successfully used for many years at a number of major petrochemical plants in Belgium to repair and protect the tube sheets, water boxes, heads and end covers on many different types of heat exchangers.

These photos illustrate just some of the numerous applications that have been completed.



700 Hicksville Road • ENECON Center Suite 110 • Bethpage, NY 11714  
Toll Free: 888-4-ENECON • Phone: 516.349.0022 • Fax: 516.349.5522  
[www.enecon.com](http://www.enecon.com) • [info@enecon.com](mailto:info@enecon.com)