

After 4+ Years Of Service In An Alumina Refinery, CeramAlloy CBX Is Still In Excellent Condition



Client:

Australian Alumina Refinery

Problem:

Calciner screws, subjected to extreme abrasion typically only last 12-18 months.

This screw (image 1) was protected with CeramAlloy CBX and put back into service for over 4 years.

After brush blasting clean, the CeramAlloy CBX is shown to still be in excellent condition (image 2).



After 4+ years in service.



After cleaning, the CBX is still in excellent condition.

6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com